



Western Michigan University
ScholarWorks at WMU

Legacy Scout Tickets from Pure Oil Company

8-20-2021

**MGRRE_PureOilScoutTickets_Vos, Martin G
J_1_21139069540000**

MGRRE
Western Michigan University

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

WMU ScholarWorks Citation

MGRRE, "MGRRE_PureOilScoutTickets_Vos, Martin G J_1_21139069540000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 8750.
<https://scholarworks.wmich.edu/pure/8750>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



MGRRE_PureOilScoutTickets_Vos, Martin G J_1_21139069540000

API 21139069540000

Permit Number 6954

Lease Name Vos, Martin G J

Well Number 1

County Ottawa

Township 07N

Range 14W

Section 33

2021 DEQ or Pure co_name Weller Charles and Dapar Oil Company

Pure Number 119

Latitude 42.95305

Longitude -85.96436

THE PURE OIL COMPANY
COMPLETION RECORD OF WELLS DRILLED BY OTHER OPERATORS
LOCATION REPORT

DATE November 2, 1939

No. 119

STATE Michigan COUNTY Ottawa DISTRICT Allendale SEC. 33 TOWN 7 N RANGE 14 W
WELL No. 11 (SERIAL No. 119) FARM M. G. J. Vos ACRES NE SE NE

NAME OF STREAM OR WATERS _____ QUADRANGLE NE SE NE

OPERATOR C. E. Weller & Dapar Oil Company Map Allendale Township, Ottawa County

1651650 Dapar Oil Co. & C. E. Weller
Feet from North Line of Farm

330330 " " East " " "
" " South " " "
" " West " " "

1650 Feet from North Line of Section

330330 " " East " " "
990 990 " " South " 1/4 "
" " West " " "

○ LOCATION

① RIG

⊕ DRILLING

☼ GAS WELL

● OIL WELL

⬮ SMALL OIL WELL

LEGEND

⊖ DRY HOLE

⬮ DRY SHOWING OIL


⊖ DRY SHOWING GAS

⊖ ABANDONED LOCATION

☼ ABANDONED GAS WELL

⬮ ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

Superintendent or Foreman.

